Figure 1



Figure 2



Figure 3

Code	n	k	r
1	360	120	1/3
2	240	120	½
3	200	120	3/5
4	160	120	¾
5	120	120	1

SCANNED, # 22

Figure 4



Figure 5


Start
40
Monitor System Parameter
41
Determine Thresholds
C/I max, S max
42
Code
Shortage ?
no
43
End
yes
44
C/I > C/I min
no
45
End
yes
46
Select suitable MS
47
Measurement Report
48
Σ SBS < Smax
no
yes
49
Change Coding Rate
Release Code
End
50